



Harrison M250
280mm - 11in swing centre lathe

machine manual

machine manual

Contents

	Page No.
Summarised Specifications	2
Installation	
1) General arrangement and foundation plan	4
2) Installation instructions	5
3) Lubrication diagram	8
Operation	
1) Controls diagram	10
2) Operating instructions	11
3) Lathe operator safety	15
Maintenance	
1) Maintenance instructions	18
Parts Section	
1) Parts ordering procedure	23
2) Illustration contents list	24
3) Spare parts illustrations	25
4) Standard/Proprietary parts code list	58
Electrical Wiring Diagram	61

Machine Specification

280mm (11in) swing Centre Lathe

500mm MODEL – 500mm (20 in) between centres

750mm MODEL – 750mm (30 in) between centres

This machine is manufactured to British metric standards throughout, and is available in two bed lengths

Metric or English gear boxes and drive screws (together with the appropriate micrometer dials) are optional variations.

summarised specification

Centres	Height 145mm (5.7 in)	English Gearbox with 4 TPI Leadscrew	Threads English Pitches (56) 4 - 84 TPI
	Admits Between 500mm (20 in)		Metric Pitches (23) * 0.4 - 10mm
	or 750mm (30 in)		<i>* (available by changewheels supplied as additional equipment)</i>
Swing	Over Bed 280mm (11 in)		Feeds Longitudinal (24) . . . 0.0006 - 0.016 in
	Over Cross Slide 178mm (7 in)		Cross (24) . . . 0.0003 - 0.008 in
Spindle	Bored to Pass 35mm (1.375 in)	Bed	Width Over Ways 190mm (7.5 in)
	Nose D1-3		Depth Under Headstock 230mm (9 in)
	Morse Taper In Nose Bush 3	Cross Slide	Width 130mm (5.1 in)
Speeds	Number 9		Travel 165mm (6.5 in)
50 Hz	Range 40 - 1500 rpm	Top Slide	Width 76mm (3 in)
Machines	Motor 0.9 kW (1.2hp)		Travel 92mm (3.6 in)
or	Range 80 - 3000 rpm	Tailstock	Quill Diameter 38mm (1.5 in)
	Motor 1.3 kW (1.8hp)		Travel 95mm (3.7 in)
or	Range 40 - 1500 rpm	Weight	500mm (20 in) Centres 356 kg (785 lbs)
	Motor (Single Phase) 1.1 kW (1.5hp)		750mm (30 in) Centres 457 kg (1008 lbs)
60 Hz	Range 40 - 1500 rpm	Shipping Data	Gross Weight Packing Case Dimensions
Machines	Motor 1.5 hp		L W H
or	Range 52 - 2000 rpm	500mm (20 in) Centres	457 kg (1008 lbs) . . . 1574 x 838 x 1371mm
or	Motor 1.5 hp		(62" x 33" x 54")
	Range 52 - 2000 rpm	750mm (30 in) Centres	559 kg (1232 lbs) . . . 1828 x 838 x 1371mm
	Motor (Single Phase) 1.5 hp		(72" x 33" x 54")
Leadscrew	Diameter 25mm (0.98 in)		SPACE REQD. 65" x 27"
	Thread 6mm pitch or 4 TPI		
Metric Gearbox with 6mm pitch Leadscrew	Threads Metric pitches (33) 0.25 - 8mm		
	English Pitches (33) * 3 - 72 TPI		
	<i>* (available by changewheels supplied as additional equipment)</i>		
	Feeds Longitudinal (21) 0.012 - 0.4mm		
	Cross (21) 0.006 - 0.2mm		




standard equipment

Single Toolpost
Work Driver Plate
No. 5/3 Morse Centre Bush
2 No. 3 M.T. Centres

Spanners, Keys and Oil Gun
Machine Manual
& Standard Inspection Certificate

Illustrated or specified data is not binding in detail: The manufacturers reserve the right to modify design, specification and price without notice.

Installation



Lifting

The approximate weights of the machine are:-

500mm Model (500 mm/20'') between centres - 400 kg (880 lbs)

750mm Model (750 mm/30'') between centres - 460 kg (1010 lbs)

The machine should be lifted using a rope sling looped under both ends of the swarf tray.

Cleaning

Bright surfaces are coated with an anti-corrosive compound at despatch and this must be completely removed using White Spirit or Paraffin (Kerosene) before operating the controls or moving the slides. DO NOT USE CELLULOSE SOLVENTS. Oil the bright surfaces and slideways AFTER CLEANING. (see Lubrication diagram).

Positioning

Locate the machine on a solid foundation allowing sufficient area for operation and maintenance access. (SEE GENERAL ARRANGEMENT AND FOUNDATION PLAN).

The lathe may be used when free standing, but for maximum performance it should be bolted down.

- (1) **Free standing.** Position the machine on its foundation and adjust each of the four levelling screws to take an equal share of the weight. Then using an engineer's precision level on the bedways make further adjustments for level conditions.
- (2) **Fixed installation.** Position the machine over four 12 mm (1/2'') diameter foundation bolts, set to suit the base. (SEE GENERAL ARRANGEMENT AND FOUNDATION PLAN).

Accurately level the machine as in (1), then tighten the foundation bolts evenly to avoid distortion and finally re-check for level conditions.

Electrical Supply

Power should be supplied through an external fused isolator - recommended fuses being 15 amp for 220 volts supply and 10 amp for 380 to 440 volts supply. External wiring should be of a permanent character and be undertaken by a competent electrician. SEE GENERAL ARRANGEMENT AND FOUNDATION DRAWING FOR CABLE ENTRY.

Line connections and a substantial earth continuity conductor should be connected to the terminal block (SEE ELECTRICAL WIRING DIAGRAM).

If main spindle rotation does not coincide with that indicated by forward/reverse switch at control station, interchange two line connections.

continued

Lubrication (Refer to Lubrication diagram)

Ensure that the headstock, gearbox and apron are filled to the level of the relevant oil sight windows - and oil the cross-slide nut, dials and changewheel stud etc. through the appropriate oil nipples using the oil gun provided.

Running-in


For optimum bearing life and performance it is recommended that high spindle speeds be avoided during the initial life of the machine.

Alternatively a running-in procedure should be adopted as follows:-

**Make a low feed rate selection and run the machine light for 3 hours at 260 rpm
then for 1 hour at 550 rpm
then for ½ hour at 750 rpm**


Lubrication

Check levels and oil daily
 Schauglas und Öl täglich überprüfen
 Vérifier les regards et graisser quotidiennement



Mobil	BP	Castrol	C	ESSO	Shell	TEXACO
DTE OIL HEAVY MEDIUM	ENERGOL HLP 68 (ISO)	HYSPIN AWS 68	P.W.L.C.	NUTO H68	TELLUS 68 OR R68	RANDO HD 68
DTE EXTRA HEAVY	ENERGOL HP 150 (ISO)	ALPHA ZN 220	WLM	NURAY 220	VITREA 220	REGAL R & O 220

Operation



- | | | |
|------------------------------|--|-------------------------------------|
| 1. MAINS ISOLATOR | 9. SPEED SELECTOR LEVER | 17. TAILSTOCK SET-OVER SCREW |
| 2. FORWARD/REVERSE SWITCH | 10. SPEED RANGE SELECTOR DIAL | 18. CARRIAGE LOCK |
| 3. COOLANT ON/OFF SWITCH | 11. TOP SLIDE LOCK | 19. CROSS TRAVERSE HANDLE |
| 4. EMERGENCY STOP PUSHBUTTON | 12. TOP SLIDE TRAVERSE HANDLE | 20. TREADCUTTING ENGAGEMENT |
| 5. START PUSHBUTTON | 13. QUILL LOCK | 21. FEED AXIS SELECTOR |
| 6. FEED SELECTOR | 14. TAILSTOCK CLAMP | 22. FEED ENGAGE |
| 7. FEED SELECTOR | 15. QUILL TRAVERSE HANDWHEEL | 23. LONGITUDINAL TRAVERSE HANDWHEEL |
| 8. FEED DIRECTION SELECTOR | 16. CROSS-SLIDE LOCK (in R.H. side of cross slide) | |

Starting the Machine

1. Ensure that lubrication has been carried out in accordance with the Lubrication diagram.
2. Check that the feed engage lever (22) and thread-cutting lever (20) are in the disengaged positions and that the changewheel cover is firmly secured in place.
3. **Select - Feed Axis** - i.e. cross or longitudinal by means of the apron push-pull knob (21).
Select - Direction of feed - by means of the headstock lower selector (8)
Select - Feed Rate - by referring to the charts on the headstock and selecting (in the sequence listed) the appropriate positions on the gearbox selectors (6) and (7). (Engagement of the feed gears may be assisted by turning the main spindle)
Select ** Spindle speed by turning the speed range selector dial (10) to present the appropriate range i.e. A B or C, then turn the speed selector lever (9) to point to the required speed from the chart.
(Engagement of the drive gears may be assisted by manually turning the spindle)
4. Switch on the electrical supply at the mains isolator (1) which is the red knob at the L.H. end of control station.
5. Select direction of spindle rotation by means of forward/reverse switch (2).
6. Start the spindle by means of start push-button (5).
7. Start and stop the feed motion as required by means of the feed engage lever (22)

Stopping the Machine

The machine may be stopped by the Emergency Stop pushbutton (4).

Operational Notes

FACEPLATES

NOTE MAXIMUM SPEEDS:-

1500 rpm for 260 mm (12") dia.

COARSE SCREWCUTTING/
FEED RANGE 'J'

SHOULD NOT BE USED WITH
SPINDLE SPEEDS ABOVE 750 RPM.

NOTES

** See Installation instructions (RUNNING-IN) if starting the machine for the first time.

continued

Operational notes continued

Micrometer dials are direct reading (for work piece diameter reduction on the cross-slide) and are of the friction-grip type for easy index settings.

Longitudinal traverse handwheel (23) may be disengaged by pulling it away from the apron face.

Tailstock set over adjustment - is provided in the form of socket screws (17) mounted in each side of the tailstock body, - a similar but 'location-screw' is fitted in the rear face of the body.

Set-over adjustment is made as follows: -

Unclamp the tailstock - (lever 14)

Slacken the rear 'location-screw' (say one half turn)

Then - Alternatively slacken one set-over screw and tighten the other until the required setting is achieved.

Tighten the rear 'location-screw'

And Re-clamp the tailstock.

Leadscrew Drive

Drive to the leadscrew is obtained by first removing the torque limiter cover plate. Then slide the driving sleeve towards the gearbox so engaging the shear pin with the leadscrew shaft. When not in use it is recommended that the leadscrew be disengaged.

MOUNTING OF CHUCKS, FACEPLATES and other SPINDLE MOUNTED ATTACHMENTS.

Ensure that the location faces on both nose and attachment are scrupulously clean.

Check that all the cams are in the release position (Fig. 1).



Mount the attachment on to the spindle nose and lock each cam by turning it clockwise using the key provided.

A reference line R1 (Fig. 1) should be scribed on each chuck or faceplate to coincide with the reference line R on the spindle nose. This assists subsequent re-mounting

NOTE:-

For correct locking conditions each cam must tighten with its index line between the two vee marks on the nose (Fig. 2).

DO NOT INTERCHANGE CHUCKS OR OTHER SPINDLE MOUNTING ITEMS BETWEEN LATHES WITHOUT CHECKING EACH CAM FOR CORRECT LOCKING.



TO ADJUST 'CAMLOCK STUDS'


Remove Lockscrew (B).

Turn Stud (A) one full turn, in or out as required.

Re-fit and tighten lockscrew (B).

NOTE:-


A datum ring (C) is marked on each stud as a guide to the original or initial setting.



Spindle Nose


Changewheel Combinations

Fig. 2A for Metric Leadscrew Machines



6 mm. pitch Leadscrew

Fig. 2B for English Leadscrew Machines




4 tpi. Leadscrew



Thread – cutting

THREADCUTTING - METRIC GEARBOX



STANDARD THREADS AVAILABLE



 mm									
0.25	N3F	0.7	M1F	1.2	K1G	2	L2G	3.5	M2H
0.3	K3F		M3G		K3H		N1H	4	L2H
0.35	M3F	0.75	K2F	1.25	N2G		N3J		N1J
0.40	L3F	0.8	L1F	1.4	M1G	2.4	K1H	4.8	K1J
0.5	N1F		L3G		M3H		K3J	5	N2J
	N3G	0.875	M2F	1.5	K2G	2.5	N2H	5.6	M1J
0.6	K1F	1	L2F	1.6	L1G	2.8	M1H	6	K2J
	K3G		N1G		L3H		M3J	6.4	L1J
0.625	N2F		N3H	1.75	M2G	3	K2H	7	M2J
						3.2	L1H	8	L2J
							L3J		

THREADS AVAILABLE WITH ADDITIONAL CHANGEWHEELS

ins					
		W	X	Y	Z
72	N3	30	81	40	84
64	N3	35	84	40	84
56	N3	40	84	40	84
48	N3	40	84	40	72
40	N3	22	88	80	63
36	N3	30	81	60	63
32	N3	35	84	60	63
28	N3	30	84	80	63
27	N3	30	81	80	63
26	N3	30	78	80	63
25	L3	22	88	80	63
24	N3	35	84	80	63
23	N3	40	92	80	63
22	N3	40	88	80	63
20	K3	35	84	80	63
19	N3	40	76	80	63
18	N3	40	72	80	63
16	N2	22	88	80	63
14	N1	30	84	80	63
13	N1	30	78	80	63
12	N1	35	84	80	63
11.5	N1	40	92	80	63
11	N1	40	88	80	63
10	K1	35	84	80	63
9	N1	40	72	80	63
8	K2	35	84	80	63
7.5	L1	35	84	80	63
7	L2	30	84	80	63
6	L2	35	84	80	63
5	K1	60	72	80	63
4.5	L2	40	72	80	63
4	K2	60	72	80	63
3	L2	60	72	80	63

993


				
MOD		X	Y	Z
.3	K3	22	88	56
.4	L3	22	88	56
.5	N1	22	88	56
.6	K1	22	88	56
.7	M1	22	88	56
.8	L3	44	88	56
1	N1	44	88	56
1.25	N2	44	88	56
1.5	K2	44	88	56
1.75	M2	44	88	56
2	L2	44	88	56
2.5	N2	44	88	28
3	K2	44	88	28
3.5	M2	44	88	28

					
DP		W	X	Y	Z
56	N3	44	98	100	63
48	N3	44	84	100	63
40	N3	55	81	72	49
36	N3	44	81	100	49
32	N3	55	56	80	63
28	N3	55	63	80	49
24	N3	55	63	80	42
22	N3	60	63	80	42
20	K3	55	63	80	42
18	N1	44	81	100	49
16	N2	44	63	80	56
14	N1	55	63	80	49
12	N1	55	63	80	42
11	N1	60	63	80	42
10	K1	55	63	80	42
9	L2	44	81	100	49
8	K2	55	63	80	42





1037

THREADCUTTING - ENGLISH GEARBOX


STANDARD THREADS AVAILABLE


 ins									
3.1/8	K2J	8	M2H	13.3/4	R1H	25.1/3	K2F	44	M1F
4	M2J	8.71	K1H	14	S2H	26	L2G	48	M3F
4.35	K1J	8.15/16	L1J	15	R3H	27	T3G	49.1/2	T1F
4.1/2	T2J	9	T2H	16	M2G	27.1/2	R1G	52	L2F
4.3/4	K3J	9.1/2	K3H	17.42	K1G	28	S2G	54	T3F
5	R2J	9.5/8	S1J	17.7/8	L1H	30	R3G	55	R1F
5.1/2	M1J	9.3/4	L3J	18	T2G	32	M2F	56	S2F
6	M3J	10	R2H	19	K3G	34.83	K1F	60	R3F
6.3/16	T1J	10.1/2	S3J	19.1/4	S1H	35.3/4	L1G	71.1/2	L1F
6.1/3	K2H	11	M1H	19.1/2	L3H	36	T2F	77	S1F
6.1/2	L2J	12	M3H	20	R2G	38	K3F	78	L3G
6.3/4	T3J	12.3/8	T1H	21	S3H	38.1/2	S1G	84	S3F
6.7/8	R1J	12.2/3	K2G	22	M1G	39	L3G		
7	S2J	13	L2H	24	M3G	40	R2F		
7.1/2	R3J	13.1/2	T3H	24.3/4	T1G	42	S3G		

THREADS AVAILABLE WITH ADDITIONAL CHANGEWHEELS

ins				
				
11 1/2	M1			
mm				
				
		X	Y	Z
.4	R3	21	100	45
.5	M3	21	100	45
.6	R2	21	100	45
.7	M3	21	100	63
.75	M2	21	100	45
.8	M3	24	100	63
1	M3	24	80	63
1.2	M2	24	100	63
1.25	M2	22	88	63
1.4	R2	28	80	63
1.5	M2	24	80	63
1.6	R2	40	100	63
1.75	M2	28	80	63
1.8	R2	45	100	63
2	R2	40	80	63
2.2	R2	44	80	63
2.25	M2	45	100	63
2.4	R2	48	80	63
2.5	M2	40	80	63
2.75	M2	44	80	63
2.8	R2	42	60	63
3	M2	48	80	63
3.2	R2	48	60	63
3.5	M2	42	60	63
3.75	M2	45	60	63
4	M2	48	60	63
5	R2	60	48	63
6	R2	60	40	63
6.25	M2	60	48	63
7	R2	63	40	70
7.5	M2	60	40	63
8	R2	63	40	80
10	M2	63	40	80

1035


				
DP		X	Y	Z
56	S2	22	88	56
48	M3	22	88	56
40	R2	22	88	56
36	T2	22	88	56
32	M2	22	88	56
28	S2	44	88	56
24	M3	44	88	56
22	M1	44	88	56
20	R2	44	88	56
18	T2	44	88	56
16	M2	44	88	56
14	S2	44	88	28
13	L2	44	88	28
12	M3	44	88	28
11	M1	44	88	28
10	R2	44	88	28
9	T2	44	88	28
8	M2	44	88	28

					
MOD		W	X	Y	Z
.4	R3	45	100	66	80
.5	M3	45	100	66	80
.6	R2	45	100	66	80
.7	M3	63	100	66	80
.8	R3	30	100	99	40
1	M3	30	100	99	40
1.25	M2	30	100	99	48
1.5	M2	30	100	99	40
1.75	M2	42	100	99	48
2	R2	44	88	99	40
2.25	M2	45	100	99	40
2.5	M2	44	88	99	40
2.75	M2	44	80	99	40
3	M2	48	80	99	40
3.5	M2	56	80	99	40

1038

(A) METRIC THREADS on METRIC LEADSCREW MACHINES
 or
ENGLISH THREADS on ENGLISH LEADSCREW MACHINES

For these threads it is recommended that the "thread indicator dial" be used - this allows the leadscrew nuts to be disengaged at the end of each screwcutting pass, provided that they are re-engaged in accordance with the chart mounted on the front face of the dial unit.



METRIC LEADSCREW MACHINES
(METRIC THREADS ONLY)

The chart shows:-

- in column 1. mm pitch to be cut.
- in column 2. (*) The requisite gear of the double pinion should be arranged to mesh with the leadscrew.
- in column 3. The dial numbers at which the leadscrew nuts may be engaged.

mm

0.25	20	14	1.4	21	135
0.3	20	14	1.5	20	14
0.35	21	135	1.75	21	135
0.4	20	14	2	20	14
0.5	20	14	2.5	20	14
0.6	20	14	3	20	14
0.7	21	135	3.5	21	135
0.75	20	14	4	20	14
0.8	20	14	5	20	14
1	20	14	6	20	14
1.2	20	14	7	21	135
1.25	20	14	8	20	1

ENGLISH LEADSCREW MACHINES
(ENGLISH THREADS ONLY)

The chart shows:-

- in column 1. T.P.I. to be cut.
- in column 2. Dial numbers at which the leadscrew nuts may be engaged.

ins

4	1-6	11	1-6	28	1-6
4½	135	12	1-6	30	1-6
5	1-6	14	1-6	32	1-6
5½	135	15	1-6	36	1-6
6	1-6	16	1-6	38	1-6
6½	135	18	1-6	40	1-6
7	1-6	19	1-6	44	1-6
7½	135	20	1-6	48	1-6
8	1-6	22	1-6	52	1-6
9	1-6	24	1-6	54	1-6
9½	135	26	1-6	56	1-6
10	1-6	27	1-6	60	1-6

(B) ENGLISH THREADS on METRIC LEADSCREW MACHINES
 or
METRIC THREADS on ENGLISH LEADSCREW MACHINES
 or
ALL THREADS ON MACHINES NOT FITTED WITH THREAD INDICATOR

For these threads the leadscrew nuts are kept engaged throughout the cutting of any one thread. This involves reversing the whole drive by means of the reverse switch (2) at each end of the screwcutting pass whilst at the same time relieving or increasing the cut as required.

(Threads 'A' may also be cut by this method).

LATHE OPERATOR SAFETY

Harrison Lathes are fast, powerful machines which can be dangerous if used under improper circumstances. Please read and observe the following Health and Safety Guidance Notes before and during the use of the machine.

HEALTH AND SAFETY AT WORK ETC. ACT 1974

In accordance with the requirements of the Health and Safety at Work etc. Act 1974 this manual contains the necessary information to ensure that the machine tool can be operated properly and with safety. It is assumed that the operator has been properly trained, has the requisite skill and is authorised to operate the machine, or, if undergoing training, is under the close supervision of a skilled and authorised person.

Attention is drawn to the importance of compliance with the various statutory regulations which may be applicable, such as "The Protection of Eyes Regulations". It is further stressed that good housekeeping, common sense and the maintenance of good established work shop practice is essential.

Adequate information is also provided to enable the machine to be properly serviced and maintained by persons with the necessary skills and authority. It is recommended that a "Permit to Work" system, such as that detailed in Code of Practice BS 5304; 1974. Safeguarding of Machinery should be operated.

MACHINE CAPACITY

The dimensions of a component which can be accommodated on the M250 lathe are limited only by the physical restrictions of the machine itself but responsibility for the following points with respect to machining a component must inevitably rest with the user.

- (1) Ensuring that the operator has had suitable training and possesses the required degree of skill and experience to undertake the work.
- (2) Providing suitable work holding and/or supporting equipment, i.e. chucks, steadies, revolving centres, etc.
- (3) Ensuring that suitable tooling is provided and correctly mounted.
- (4) Ensuring that suitable feeds and speeds are selected (if in doubt select the lowest).
- (5) Providing suitable workpiece guards and ensuring that these are consistently used.

IMPORTANT SAFETY NOTE ON ALL MACHINES

Because of the possibility of bodily contact and whipping, especially when small diameters of material are used, bar stock must NOT, under any circumstances, be allowed to extend beyond the end of the headstock spindle without the use of special guarding and adequate support.

OPERATING SAFETY PRECAUTIONS

1. Keep the machine and work area neat, clean and orderly.
2. Ensure all guards and cover plates are in place and all machine cabinet doors closed before starting machine.
3. Never lay anything on the working surfaces of the machine, or inside the machining chamber, where it may foul with rotating or moving parts.

4. Do not touch or reach over moving or rotating machine parts.
5. ENSURE YOU KNOW HOW TO STOP THE MACHINE BEFORE STARTING IT.
6. Do not operate the machine in excess of its rated capacity.
7. Do not wear rings, watches, ties or loose sleeved clothing.
8. STOP MACHINE IMMEDIATELY ANYTHING UNEXPECTED HAPPENS.
9. DO NOT interchange chucks or other spindle mounting items without checking for correct locking (see Operational Notes).
10. Do not use other workholding devices without checking for compatibility with T.S. Harrison and Sons Ltd. and workholding manufacturer.
11. Check load capacity of revolving centres for application in hand.
12. Stop motors and switch off isolator when leaving machine unattended.

OPERATING HAZARDS

When using the machine be **FULLY AWARE** of the following operating hazards detailed under the following instructions:

a) Cancer of the Skin Caused by Oil

Cancer of the skin may be produced by continuous contact with oil, particularly with straight cutting oils, but also with soluble oils. The following precautions should be taken:

1. Avoid unnecessary contact with oil.
2. Wear protective clothing.
3. Use protective shields and guards.
4. Do not wear oil soaked or contaminated clothing.
5. Use barrier creams provided.
6. Do not wash hands in coolant.
7. After work thoroughly wash all parts of the body that have come into contact with oils.

b) Safe Operation of Lathe Chucks

Where details of operating speeds and of maximum recommended operating speeds are supplied these are intended only as a guide. Such details must be regarded as for general guidance only for the following reasons:

They apply only to chucks in sound condition.

If a chuck has sustained damage, high speeds may be dangerous. This applies particularly to chucks with grey cast iron bodies wherein fractures may occur.

The gripping power required for any given application is not known in advance.

The actual gripping power being used for any given application is not known by the chuck manufacturer.

There is the possibility of the workpiece becoming insecurely gripped due to the influence of centrifugal force under certain conditions. The factors involved include:—

- (a) Too high a speed for a particular application.
- (b) Weight and type of gripping jaws if non-standard.
- (c) Radius at which gripping jaws are operating.
- (d) Condition of chuck — inadequate lubrication.
- (e) State of balance.
- (f) The gripping force applied to the workpiece in the static condition.
- (g) Magnitude of the cutting forces involved.
- (h) Whether the workpiece is gripped externally or internally.

Careful attention must be paid to these factors. As they vary with each particular application, a manufacturer cannot provide specific figures for general use, the factors involved being outside his control.

GENERAL PRINCIPLES CONCERNING OPERATOR SAFETY FOR ALL TURNING MACHINES

1. Do not hold a lathe part with grease or oil on it.
2. Hold all lathe parts firmly.
3. Do not attempt to hold lathe parts that are too awkward or too hard to hold.
4. Do not hold or lift lathe parts that weigh too much.
5. Know how to properly hold lathe parts when lifting.
6. Use the correct type of sling when lifting workpieces or equipment by crane.
7. Stand clear when lifting workpieces or equipment by crane.
8. Obtain assistance when mounting heavy or awkwardly shaped workpieces.
9. Be sure to clean oil or grease from hand tools and levers and handles.
10. Be sure there is enough texture on the surface of the hand tool or lever handle for proper safe hand contact.
11. Hold hand tools and lever handles firmly.
12. Always choose the proper hand tool and appropriate hand position on the lever handle.
13. Do not use hand tools or lever handles in an awkward position.
14. Always use the recommended number of hands to grasp hand tools and lever handles.
15. Do not get turning or hand tools caught in the chuck or other holding device.
16. Do not use broken or chipped tools.
17. Be sure work piece cannot move in chuck or other holding device.
18. Beware of irregular shaped work pieces.

19. Beware of burrs on work pieces and remove if possible.
20. Always select the proper tool for the job.
21. Always attend to your lathe operation – do not run the machine unattended.
22. Do not use tools without handles.
23. Do not apply too much pressure with tools.
24. Do not use defective tools.
25. Always secure your work piece.
26. Always completely secure tool in sockets and screw slots.
27. Do not rely on work tool sockets, screw slots, nuts or bolts.
28. Do not rely on fasteners beyond your reach.
29. Beware of obstructions that prevent complete tightening of fasteners.
30. Do not work in a hurry.
31. Do not overtighten equipment.
32. Never substitute the wrong size tools if the correct size tool is not available in the shop.
33. Never substitute the wrong sized tool if you cannot locate the correct tool in the shop.
34. Do not move guards while lathe is under power.
35. Do not place hand or body part in path of moving parts.
36. Beware of touching lathe parts that will move or fall.
37. Be aware of where you are moving your hand or body part.
38. Beware of holding a tool or other parts inserted in or attached to the chuck or work piece.
39. Be aware of hand or other body part that is in position to be hit by a chuck or work piece.
40. Be aware of your resting position.
41. Do not lean on the machine.
42. Beware of accidentally engaging clutch or turning the power on.
43. Know your controls.
44. Read and understand operation notes before attempting to use the machine.
45. Do not touch revolving chuck, spindle or work piece.
46. Never place your hand on chuck, spindle, or work piece to stop rotation of the lathe.
47. Make sure clutch is disengaged.
48. Make sure power has been turned off.
49. Beware of chuck drifting to a stop before operating it.
50. Always check chuck area.
51. Never engage power with chuck wrench in the chuck.
52. Remove the chuck key immediately after use.

53. Do not operate lathe while talking.
54. Keep your mind on the job.
55. Beware of lathe dangers when attending to other aspects of lathe operation.
56. Beware of loose clothing near the rotating parts of the lathe.
57. Button up overalls and roll up sleeves or button the cuffs.
58. Beware of loose hair near the rotating parts of the lathe.
59. Keep hair short or wear a cap and hair net.
60. Beware of performing another operation while in close proximity to rotating parts on the lathe.
61. Be aware when changing body positions.
62. Always attend to filing and deburring operations.
63. Always pay attention to file or deburring tools close to the chuck.
64. Files and deburring tools may catch on chuck.
65. Beware of clutch position when jogging the spindle to different positions for gauging.
66. Beware of hands resting on clutch levers.
67. Be sure lathe is in neutral position when placing gauges on components gripped in the chuck.
68. Be sure motor is not running when using gauges on the machine.
69. Be sure speed is set at 0 RPM when placing gauges on mounted workpieces.
70. Always wear protection before operating the lathe.
71. Always wear the right protection before operating the lathe, i.e. safety glasses, overalls, protective shoes, etc.
72. Never remove protection for even a short time when operating the lathe.
73. Wear protective devices correctly.
74. Know the correct way to wear protective devices.
75. Beware of foreign material flying from the lathes.
76. Keep protective shields at the point of operation.
77. Know how to set or attach protective guards properly.
78. Never use the wrong protective guard.
79. Know how to select the proper guards.
80. Never reach over, under or around a work piece to make an adjustment.
81. Never reach over, under or around a work piece to retrieve a hand tool or lathe part.
82. Beware of where you leave your tools during set up.
83. Never reach over, under or around work piece to move hand tool/lathe to another position.
84. Never reach over, under or around the work piece to tighten a lathe part.
85. Never reach over, under or around work piece to remove cuttings.

86. Beware of time/space relationships.
87. Beware of weight/force relationships.
88. Know the proper procedure for applying force.
89. Never apply force from an awkward position.
90. Never mount a work piece too large for the lathe to handle.
91. Never mount a work piece too large for the worker to handle.
92. Use the equipment necessary for handling work pieces.
93. Never apply more force on the accessory or control lever than you can handle.
94. Secure all work pieces.
95. Secure all jaws, nuts, bolts and locks.
96. Avoid unsafe procedures.
97. Never use undersized parts.
98. Always use the proper equipment.
99. Tighten all fasteners.
100. Never take excessive cuts in machine operation.
101. Never use excessive force in polishing, filing and deburring.
102. Always use the proper hand tool to remove cuttings.
103. Never hurry to remove cuttings.
104. Beware of cuttings wrapped around the chuck or work piece.
105. Never change gears by moving item with your hands.
106. Never remove gear guards.
107. Beware of tools/lathe parts falling on controls.
108. Do not remove swarf with bare hands, use a rake or a brush.
109. Do not interfere with electrical equipment.
110. Do not keep tools in overall pockets.
111. Report any accident, however small, immediately it happens.
112. Use only high speed chucks.
113. Note maximum permissible speeds of faceplates (see operational notes).
114. Check — spindle control lever is in stop position before starting motors
spindle speed selected
feed rate selected
direction of feed, and that feed and thread cutting levers are disengaged
before starting the spindle
115. Do not remove work from the machine without retreating the tool to a safe position.

Maintenance




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

Changewheel Shear Pin (Fig. 1)

A protection against accidental overload in the end gear train is provided in the form of a shear pin fitted in the splined sleeve on the top changewheel shaft. In the event of replacement being necessary a 4 mm (5/32") diameter x 20 mm (3/4") long mild steel pin should be fitted as follows:-

Remove the hexagon nut, washer and changewheel, pull off the splined sleeve and remove the broken pin parts from both sleeves and shaft. Fit new pin.

NOTE: The pin acts in single shear and will only enter the sleeve from the "big-hole" side.

Leadscrew Shear Pin (Fig.2)

A shear pin device is incorporated on the leadscrew adjacent to the gearbox, as protection against overload. Instructions for replacing the shear pin are as follows:-

Remove the torque limiter cover plate.

Disengage shear pin assembly by sliding away from gearbox face.

Rotate spring steel cover on its locating sleeve until access slot is exposed.

Release M5 dog-point set screw in sleeve and rotate sleeve and cover until shear pin is exposed through slot.

Replace shear pin as shown in illustration (2) and re-assemble ensuring that the dog point of the M5 set screw is correctly located.

Drive Belts (Fig. 3 and 4)

Access to the Drive Belt is gained by removal of the moulded end guard when vee Belt tension may be assessed by applying finger pressure on the belt at a point midway between the two pulleys (fig. 3). For correct tension a deflection of about 10 mm should be possible.

To adjust the vee belt tension – release the lock nut on the adjusting screw (fig. 4) to increase tension, tighten screw against the bed until correct tension is obtained then re-tighten lock nut.

It is important that when making adjustments a straight edge be placed across the face of each pulley to ensure that correct alignment is maintained.

Saddle Strips (Fig. 5 and 6)

Wear on the rear and front saddle strips may be accommodated by adjustment of the retaining sleeves located in the top face of the saddle; two for the rear and one each for the two front strips.

The procedure for adjustment is to first release the socket head screw, slightly turn the slotted head sleeve anti-clockwise and then re-clamp the cap screw. Care should be taken to avoid over adjustment; a 30° turn at the sleeve represents approximately 0.1 mm (.004") take up in the strip.

Tailstock Bed Clamp (Fig. 7)

The angular lock position of the bed clamp lever is adjusted by means of the self-locking hexagon headed bolt located on the underside of the tailstock and between the bed ways.

continued

Cross-slide (Fig. 8)

Wear on the taper-gib strip may be adjusted for by clockwise rotation of the slotted head screw on the front face of the cross-slide. The procedure being to first slacken the similar screw at the rear then re-tighten this after adjustment to clamp the strip in its new position.


Top Slide (Fig. 9)


Take up for wear on the top slide strip is by means of the four (self-locking) socket set screws in the front face of the top slide casting.

Cross-slide Nut (Fig. 10)

Provision is made for the elimination of backlash in the cross-slide nut, the procedure for adjustment being as follows:-

Release only the rear pair of socket cap head screws in the top face of the cross-slide, which allows a spring loaded device to automatically remove backlash. Re-tighten cap head screws.





The spindle bearing assembly is carefully set before despatch of the Lathe from our Works which should ensure a high standard of performance without the need for further attention.

THE USER IS ADVISED NOT TO DISTURB THIS SETTING DURING NORMAL USE OF THE MACHINE AND TO CONSULT OUR SERVICE DEPARTMENT IN THE UNLIKELY EVENT OF A BEARING PROBLEM.

WHERE ADJUSTMENT IS UNDERTAKEN THEN IT IS ESSENTIAL THAT THE FOLLOWING PROCEDURES ARE STRICTLY COMPLIED WITH.

TO CHECK FOR CORRECT SETTING

Checks should be carried out with the headstock in a warm condition achieved by running at a spindle speed of 800 rpm for approximately ten minutes.

The correct bearing torque setting is 0.9/1.1 Nm (8/10 in lbs) and can be determined as follows (Fig. 1):-

- Wrap a length of string approximately three turns around the body of the chuck.

- To the free end of the string attach a light spring balance and pull gently until spindle commences to turn, continuing to apply a steady load just sufficient to maintain the spindle in motion and noting the steady load registered on the balance.

Example: Using a 160 mm (6¼ in) chuck, the spring balance reading should be 1.14/1.36 kg (2½/3 lbs).

BEARING ADJUSTMENT

Remove end drive guard, changewheels, swing frame and rear bearing cover.


Release locking screw in the bearing adjusting nut, Fig. 2. With a pin key adjust the nut as required - clockwise rotation to increase bearing load, Fig. 3. As over tightening will seriously impair the life of the bearings it is recommended that adjustment be made in increments not exceeding 3 mm (1/8 in) measured on the nut periphery. After each incremental adjustment, the spindle should be run for a few minutes and the bearing load re-checked, as described above.

Parts Ordering Procedure

1

**Quote:
Machine Serial Number**

which will be found stamped into the front face of the bedways at the tailstock end



2

Refer to the appropriate assembly and

**Quote:
Individual Part Numbers taken direct from the Illustrations**

NOTE: Quantity used (when other than one) is given in a circle following the Part Number itself.

Where part numbers change with machine bed length then the model number is given, vis.

500

or


750

Standard/Proprietary Parts (i.e. items which can be purchased from local Engineering suppliers) may be identified by the "bracketed" letter code included in the Part Number, and reference to the appendix at the end of this manual will provide a full description of such items.

Parts Section


Contents List

		Page No.
901/1	Bed and cabinet	25
901/2	Drive	26
901/3	Changewheel guard	27
902/1	Headstock	28
902/2	Headstock gears	29
902/3	Headstock controls	30
903/1	Gearbox casting and shafts	31
903/2	Gearbox gears and shafts (Metric)	32
903/3	Gearbox gears and shafts (English)	33
904/1	Apron casting and controls	34
904/2	Apron shafts	35
905/1	Saddle	36
905/2	Slides	37
906	Shafts, rack and bracket	38
907	Tailstock	39
908	Changewheels and swing frame	40
910	Standard equipment	41
911	Additional equipment (see section list)	42
912	Taper turning attachment	56
913	Bed capstan unit	57



901/1

0924 403751



901/2

KEY TO DRIVE ASSEMBLY COMPONENTS (901/2)

1

2

3


4

5


6

MOTOR		TOP SPEED SPINDLE	TOP PULLEY	MOTOR PULLEY	KEY	MOUNTING BRACKET	BELTS
D80	3 PH 50Hz	1500 3000	902010	901012	6x5x40 (KR)	901007	SPZ 800
D90S	Single PH 50Hz	1500	902053	901023	8x7x32 (KR)	901037	NU-T-Z/10(40°) Brammer ②
D80	3 PH 60Hz	1500 3000	902010	901028	6x5x40 (KR)	901007	SPZ 800
LS145T	3 PH 60Hz	1500	902010	901013	3/16"x3/16"x1.3/8"(KS)	901008	SPZ 800
LS145T	3 PH 60Hz	2000	902057	901026	3/16"x3/16"x1.3/8"(KS)	901008	SPZ/3V 787
EL145T	Single PH 60Hz	2000	902061	901033	3/16"x3/16"x1.3/8"(KS)	901008	SPZ/3V 787
EL145T	Single PH 60Hz	1500	902089	901051	3/16"x3/16"x1.3/8"(KS)	901008	SPZ 800

1035 – METRIC THREAD ENGLISH GEARBOX
 1145 – ENGLISH THREAD METRIC GEARBOX




901/3




902/2


metric




903/2




904/1






905/1



905/2




STANDARD

- 22T - 908.022
- 40T - 908.040
- 44T - 908.044
- 80T - 908.080
- 88T - 908.088
- 92T - 908.092


OPTIONAL

- 21T - 908.021
- 24T - 908.024
- 28T - 908.028
- 30T - 908.030
- 35T - 908.035
- 42T - 908.042
- 45T - 908.045
- 48T - 908.048
- 49T - 908.049
- 55T - 908.055
- 56T - 908.056
- 60T - 908.060
- 63T - 908.063
- 66T - 908.066
- 70T - 908.070
- 72T - 908.072
- 76T - 908.076
- 78T - 908.078
- 81T - 908.081
- 84T - 908.084
- 98T - 908.098
- 99T - 908.099
- 100T - 908.100


908




M8/13mm x 15mm (WRS)
M10/17mm x M12/19mm (WRS)
M14/22mm x M16/24mm (WRS)
M18/27mm x M22/32mm (WRS)




TH15



910009



L5-585A




910001


D101H2094

M12x25
(FY)

D220H1013



910006



2.5mm (FK)
3mm (FK)
4mm (FK)
5mm (FK)
6mm (FK)
8mm (FK)

M6x12 (FY) ③

910005 ③

F60
(OIL GUN)



910

Additional Equipment

		Page No.
911.09	American Toolpost	42a
911.10	4-way hard-indexing toolpost	43
911.11	Quick-change toolpost	44
911.12	Quick-change parting off toolholder	44
911.14	Chuck guard assembly	45
911.31	Saddle mounted chip guard	46
911.32	Perspex chip guard-magnetic base	47
911.35	Coolant pump tank and fittings	48
911.38	Low-voltage machine light	49
911.41	Travelling steady	50
911.42	Stationary steady	51
911.45	5-position stop-cross-slide traverse	52
911.46	Single stop - saddle traverse	52
911.47	Micrometer stop - saddle traverse	52
911.48	5-position stop - saddle traverse	52
911.60	Magnetic based dial indicator - Metric graduations	47
911.61	Magnetic based dial indicator - English graduations	47
911.67	Thread dial indicator assembly	53
911.81	Emergency foot switch	54

Parts available as assemblies (not illustrated):

911.65	Metric/English dual reading dial - Cross-slide (English cross-slide screw and nut required)
911.66	Metric/English dual reading dial - Topslide (English topline screw and nut required)
911.72	Wattmeter
1542-21601	4-jaw chuck
1212-21305	3-jaw chuck
D911H007.1	Faceplate

M10 x 40(FZ)


911.053

911.052

911.051


911.054

911/09





911/10

911/11




911/12







911/14




911/31


911/32




911/60-61




911/35







911/41






911/42

911/46




911/47


911/48



911/45



911/67



3223(1.5mm²)
(BICC)

M10(WN)A/R

M8x10x16(FU)②

SG414 ②

M8(WN)②

M8x12(FY)

M4x36(FY)②

MV3HM6S
(BURGESS)

311.81.003

M6x20(FH) ②


911/81

911004 (500mm)
911005 (750mm)


252 ②
(ELKAY)

Attachments

	Page No.
912 Taper turning attachment	56
913 Bed capstan unit	57



912



913

Standard/Proprietary Parts

'Bracketed'

Letter Code Component

Letter Codes

Conventional
Description Given

Screws and Nuts

FX Socket Set (Grub) Screw: Flat Point
 FXd " " " " Dog Point (Normal)
 FXd1 " " " " Dog Point (Long)
 FXc " " " " Cone Point
 FXw " " " " Cup, knurled or 'W' Point

Thread X O/all Length

" " " "
 " " " "
 " " " "

FY Socket Head Cap Screw
 FY1 Socket Head Cap Screw (Threaded to Head)
 FV Socket Countersunk Screw
 FS Socket Button Head Screw

Thread X Length under head

" " " "
 " " " "

FU Socket Shoulder Screw

Thread X Ø Shank X Shank length

FP Socket Pressure Plug
 FPS Press Plug (Square Head)

Thread and Form

" "

FO Slotted Set (Grub) Screw

Thread X O/all Length

FT Slotted or Pozidriv Screw: Countersunk Head
 FI " " " " Raised C/sunk Head
 FR " " " " Pan Head
 FE " " " " Cheese Head

Thread X length under head

" " " "
 " " " "

Suffix 'B' for Thread Forming Type
 Suffix 'T' for Thread Cutting Type
 Suffix 'SS' for Stainless Steel

FJ Square Head (Toolpost) Screw

Thread X Length under head

FH hexagon Head Screw

Thread X Length under head

FD " " Bolt

" " " "

FN Standard Hexagon Nut

" " " "

FL " " " Locknut

" " " "

Suffix '8.8' for High Tensile Types

Suffix 'L' for 'Self-Locking' versions of the above

FZ Hammer Drive Screw

Nom Ø X Length under head

FW Wing Nut

Thread details

DN Domed Nut

Thread details

CN Castle or Slotted Type Nut

" "

FN1 Nylon Ring Locking Nut

" "

Thread Inserts

T11 Press in Type Thread Insert
 T12 Coil Type Thread Insert

Thread details

" "

Washers

WN Bright Washer: Normal Diameter
 WL " " Large Diameter
 WK Crinkle (Wavy) Washer
 WS Spring Washer: Single Coil
 WSs " " Double Coil
 WC Folded Copper Sealing Washer
 WF Felt Washer
 DS Disc Spring (Belleville Washer)




Nominal Hole Ø

" "
 " "
 " "
 " "
 " "
 " "

Nom. Hole Ø X O.D. X thickness

'Bracketed'		Conventional
Letter Code	Component	Description Given
Pins and Dowels		
GP1	Grooved Pin: Full length groove – Tight at one end	Nom. Ø X O/all length
GP2 Half length groove – Tight on end
GP3 Full length groove – Parallel
GP4 Half length groove – Tight at centre
GP5 Centre groove
PD	Dowel Pin	Nom Ø X O/all length
PB	Brass Pin or Pad
PT	Taper Pin	Nom Ø (small end) X O/all leng
PS	Split Pin	Nom Ø X O/all length
LTP	Tension Pin: Light Duty	Nom Ø X O/all length
HTP Heavy Duty
Keys		
KS	Square Parallel Key	Width X Thickness X Length
KR	Rectangular Parallel Key
KW	Woodruff Key	Width X Height X Diameter
Circlips		
CE	External Circlip: DIN 471	DIN. Ref. Nom Shaft Ø and Thickness
CE1	Round Section Circlip	Nom. Shaft Ø, Wire Ø
CE2	Inverted Retainer (Truarc)
CB	Internal Circlip: DIN 472	DIN. Ref. Nom Bore and Thickness
CR	Radial Fitting Circlip. DIN 6799	DIN Ref. Nom Ø and Thicknes
CR1	Radial Retaining Clip (Spring fix)	Nom shaft Ø
CR2	Radial Fitting Circlip BS3673/3
Plain Bearings		
DU	Composite Bearing Bush 'Glacier'	Nom Bore. O.D. and Length
DX
LB	Sintered Bronze Bush	Nom Bore O.D. and Length
Ball & Roller Bearings		
BB	Std. Ball Bearing	Nom Bore Outside Ø and Leng
BB1	Std. Ball Bearing with Shield or Seal one side
BB2	Std. Ball Bearing with Shield or Seal both sides
BB3	Std. Ball Bearing with Snap Ring
BBT	Angular Contact Ball Bearing
RB	Cylindrical Roller Bearing
For Needle Roller Brgs, Needle Thrust Races Ball Thrust Brgs. and Taper Roller Bearings – Manufacturers Name is Quoted as Letter Code – vis.		
(INA.)	(TORRINGTON)	Manufacturers Part No. Quoted
(SKF)	or (GAMET)	

'Bracketed' Letter Code	Component	Conventional Description Given
Seals		
SM	Standard Oil Seal	Nom Shaft \emptyset O.D. and Width
SF	'V' Ring Seal (FORSHEDA)	Manufacturers Part No.
RM	Standard 'O' Ring Seal	Internal \emptyset of Ring, and Section \emptyset
RM1	'Nu-Lip Ring' (Pioneer)	Manufacturers Part No.
Lubrication Equipment		
ON	Concave Oil Nipple: Drive in Type	Nom Hole \emptyset
ONI	" " " Threaded Type	Thread details
OS	Oil Sight Glass	Nom Outside \emptyset
OS1	Oil Level Glass	" "
OW	Oil Wick	Nom \emptyset X Length
For Compression and other Pipe Fitting — Manufacturers Name is quoted as Letter Code vis.		Manufacturers Part Number Quoted
(ENOTS.) or (TECALEMIT)		
Miscellaneous Items		
BJ	Ball Joint	Thread Details
SB	Steel Ball	Nom \emptyset
FK	Hexagon Wrench Key	Nom width across flats
HP	P.V.C. Hose	Nom Bore and O.D.
HC	Hose Clip	Max. Hose \emptyset
PP	Plastic Plug	Manufacturers Part Number
WRS	Standard Spanner	Std. Bolt size and width across flats
EB	Eye Bolt	Thread details
OW	Oil wick	Nom \emptyset X Length
CT	Copper tube	Nom outside \emptyset
NT1	Nylon Tube Natural	Nom Bore
NT2	Nylon Tube Blue	" "
NT3	Nylon Tube Green	" "
NT4	Nylon Tube Red	" "






EWD 901.1 Standard
 220/380/415 V 3PH 50Hz
 1500 RPM m/c / 0.9Kw Motor

KEY & COMPONENT LIST

REF	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
1Q	Main disconnect switch (isolator)	All	Kickler Modler	P-126
1K1M	Main contractor	All	Yaskawa	HE-16S
1F2	Overload relay	220V	Yaskawa	RH-103K
1T	Control circuit transformer	All	Formisni or Alt	PH-103K / A15440V
1S	Reverser switch	All	Kickler Modler	T1-322
2S	Stop switch (main motor)	All	Kickler Modler	T1-350
1X	Terminal Block	All	Klippon	BK-12
2X	Terminal Block	All	Klippon	BK-12
MACHINE MOUNTED COMPONENTS				
1M	Main motor	To suit supply voltage	GEC	0800/9KW/1.2HP 1500 RPM
1E	Watermeter	50V (500/580)	Compson Int.	05/12/188
6S	Guard limit switch	All	Burgess	KB 5E08
7S	Click stop limit switch	All	Burgess	KB 5E08
2M	Machine light unit 2 arm fitting (400/250)	All	YAHMS	(M) YAHMS
1E	Machine light unit 2 arm fitting (400/250)	All	MG Electric	AD270
1E	Transformer unit 50V (50/580/440)	50V (50/580/440)	MG Electric	MGL 4025 B05A
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 4025 B05A
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 608
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60C
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60D
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60E
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60F
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60G
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60H
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60I
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60J
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60K
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60L
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60M
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60N
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60O
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60P
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60Q
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60R
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60S
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60T
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60U
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60V
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60W
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60X
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60Y
1E	Transformer unit 25V (13/41/440)	25V (13/41/440)	MG Electric	MGT 60Z

Wiring Diagram




EWD 901.1A Standard
220/380/415 V 3PH 50Hz
2000 RPM m/c /1.5Kw motor

REF	ITEM	SUPPLY	MANUFACTURER	TYPE
KEY & COMPONENT LIST				
PANEL MOUNTED COMPONENTS				
1Q	Main disconnect switch	All	Klopper Moeller	PI-25
1K1M	Main contactor (Isolator)	All / 415V	Yaskawa	HE-16S
1F2	Overload relay	220V	Yaskawa	RH-10/6K
1T	Control circuit transformer	All	Remhart or all	220V/280V/415&440V
1S	Reverse switch	All	Klopper Moeller	TT-3-2
2S	Coil on off switch	All	Klopper Moeller	TT-3-60
3S	Start pushbutton (main motor)	All	Kilgipon	BK-12
4S	Stop pushbutton (main motor)	All	Kilgipon	BK-12
5S	Terminal Block	All		
MACHINE MOUNTED COMPONENTS				
1M	Main motor	To suit supply voltage	GEC	GD901.1SK/2 HP 1500 RPM
6S	Guard limit switch	All	Burgess	K3 ESCR
7S	Kick stop limit switch	All	Burgess	K3 ESCR
2M	Coolant pump motor	All	Burgess	(M) V3HMS
1E	Machine light unit 2 am fitting	(400/230)	MG Electric	MGL-402S B03A
2T	Transformer unit 50V (318/41/440) *440		MG Electric	MST 600
	(machine light) 25V (318/41/440)		MG Electric	MST 608
	50V (210/230/250)		MG Electric	MST 60C
	25V (210/230/250)		MG Electric	MST 60D
	50V (500/550)		MG Electric	MST 60E
1P	Wattmeter		Common Int.	057 2168

*When fitted

Wiring Diagram




KEY AND COMPONENT LIST

REF.	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
1D	Main disconnect switch (isolator)	All	Kochner Moeller	P1-25
1K1M	Limit controller	All	Yaskawa	HE-16S
1T2	Control circuit transformer	All	Yaskawa	PH-107K
1T	Control circuit transformer	All	Ranfoc or at	Primary with 110V & 12V Secondary at VA
1S	Reverse switch	All	Kochner Moeller	TT-32
2S	Coast on off switch	All	Kochner Moeller	TT-350
3S	Start pushbutton (main motor)	All	Kilipson	BK-12
4S	Stop pushbutton (main motor)	All	Kilipson	BK-12
1X	Terminal block	All	Kilipson	BK-12
2X	Terminal block	All	Kilipson	BK-12
MACHINE MOUNTED COMPONENTS				
1M	Main motor	To unit supply voltage	GEC	D 908/1,1/1,3
6S	Guard limit switch	All	Burgess	K8S EGR
6S*	Chuck guard limit switch	All	Burgess	K8S EGR
7S	Kick stop limit switch	All	Burgess	(M) V31M/S
1K1M	Coast on off motor arm fitting (M03-1250)	All	MG Electric	AG2/V1E
1E	Machine light unit 2 arm fitting (M00-400)	All	MG Electric	MGL-400 BSA
1E*	Transformer unit 10V	All	MG Electric	MGL-400 BSA
2T	Transformer light 25V	All	MG Electric	MGL-400 BSA

*When fitted

EWD 903.1 Single phase
240V 1PH 50Hz

Wiring Diagram



EWD 905.1 U.S.A.
230-460V 3PH 60Hz

Wiring Diagram

KEY AND COMPONENT LIST


REF	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
1MCS	Mains disconnect switch (Isolator)	All	Klockner Moeller	T1-2-NA
1M	Main contactor	All	Yaskawa	HE-16S
10L	Overload relay	230V	Yaskawa	RH-10/5K
10L	Emergency stop pushbutton	460V	Yaskawa	RH-10/3K
1T	Control circuit transformer	All	Formanath or ait	UL F/U/F25/3 208 230
1RS	Reverse switch	All	Klockner Moeller	460 575 Volt primary
1S	Coolant on off switch	All	Klockner Moeller	115 Volt secondary at 25VA
1PB	Start pushbutton (main motor)	All	Yaskawa	T1-3-2
2PB	Emergency stop pushbutton	All	Yaskawa	T1-3-50
1&2TB	Terminal block	All	Klippon	BK 12
MACHINE MOUNTED COMPONENTS				
1MTR	Main motor	To suit supply voltage	Brook	K145T, 1 1/2 HP, 1800RPM
1LS	Guard limit switch	All	Burgess	K88 EOR CSA/UL
2LS	Chuck guard limit switch	All	Burgess	K88 EOR CSA/UL
3LS	Kickstop limit switch	All	Burgess	(M)V3HM/6S CSA/UL
2MTR	Coolant pump motor	To suit supply voltage	MG Electric	A03/2

*When fitted


KEY AND COMPONENT LIST

REF	ITEM	SUPPLY	MANUFACTURER	TYPE
PANEL MOUNTED COMPONENTS				
1MCS	Main disconnect switch	All	Klockner Moellir	TT-25 NA
1M	Main connector	All	Yates	HE-185
10L	Overload relay	All	Yates	RH-10/10K
1T	Control circuit transformer	All	Romash or alt	220V primary with
1RS	Reverse switch	All	Klockner Moellir	118V secondary
1S	Coastan on/off switch	All	Klockner Moellir	TT-350/NA
1PB	Start button	All	Yates	TT-350/NA
2PB	Stop button	All	Yates	TT-350/NA
1&2TB	Terminal block	All	Klipspring	BK-12
MACHINE MOUNTED COMPONENTS				
1MTR	Main motor	All	Brook	K145T, 1HP
1LS	Guard limit switch	All	Brook	1800RPM Name
2LS	Chuck limit switch	All	Burgess	KEE EGR CSA/UL
3LS	Kickstop limit switch	All	Burgess	1800RPM Name
2MTR	Coastan pump motor	All	M G Electric	(M) 230VMS CSA/UL AG3Z CSA/UL

*When fitted



EWD 907.1 Single Phase U.S.A.
220/1/60Hz



Wiring Diagram



T.S. Harrison & Sons Ltd.

Union Street, Heckmondwike, Yorkshire, England, WF16 0HN

Telephone: 0924-403751 .Telegrams: Harrison, Heckmondwike - Telex: 55217

Fax: Sales - 0924-407285

Spares/Service - 0924-411794

Illustrated or specified data is not binding in detail. The manufacturers reserve the right to modify design, specification and price without notice.

THE 600 GROUP